



Verticut Gauge




Part Number	Quantity	Description
12200-05	1 each	#4 Washer
12204-01	2 each	1/4 Washer
12413-04	2 each	#10-32 x 1/2 Socket Head Bolt
14004-03	1 each	1/4-20 x 3/8 Button Head Bolt
14004-04	1 each	1/4-20 x 1/2 Button Head Bolt
30002.12	1 each	Instruction Sheet
70069-07	1 each	Serial Number Label
73170-07	1 each	Hole Plug
77021-08	1 each	Extension
77021-10	1 each	Flat Tip
78005-01	1 each	Indicator Support
78010-01	1 each	Indicator Mount
78030-02	1 each	Tube Cap
78035-02	1 each	Case
78050-02	1 each	Spring
78065-01	1 each	Bottom Insert
78065-02	1 each	Top Insert
78070-01	1 each	Gauge Bar
78080-01	1 each	Digital Indicator


Verticut Gauge




1. While on a flat surface, loosen button screw on back of digital indicator to rotate flat tip front to back.



2. Loosen button screw inside handle to rotate flat tip left and right.



3. Once tip is flat in both directions, tighten both screws.



4. While still on a flat surface, turn indicator on and zero.